



Pricing for R44 2200-Hour Maintenance & Inspection Performed at RHC

Below pricing for R44 2200-Hour Maintenance and Inspection performed at RHC effective **01 March 2025**. Base price is for an airworthy R44 properly maintained, undamaged and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400-hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes the 2200-Hour engine overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement of 2200-hours:

Exchange Components

C006 MR Gearbox
C017 Swashplate
C018 Clutch
C021 TR Gearbox
C051 Actuator
D174 Fanwheel
Engine

New Parts

A120 Bellcrank	C169 Muffler
A190 Drive V-Belts	C170 Sheave
C008 TR Assembly	C258 Pitch Links
C016 MR Blades	C274 Windshields
C020 Upper Frame	C667 Skid Shoes
C027 Cooling Panels	C947 & A947 Flex Plates
C121-17 P/P Tube	D079 TR Guard
C005 MR Hub	D224 TR Driveshaft
C158 MR Spindles	C031 TR Pitch Control
C159 Pitch Bearings	C007-5 Fan Shaft & Bearing
Shell, Fuel Tanks	Various small parts & hardware

Base Price R44 Raven I (does not include upgrades)..... \$368,980.00 + upgrades

Base Price R44 Raven II (does not include upgrades)..... \$391,380.00 + upgrades

Base Price R44 Cadet (2400-Hours) (does not include upgrades) \$365,000.00 + upgrades

<u>Applicability</u>	<u>Description</u>	<u>Price</u>
Required thru S/N 0663	Hydraulic Flight Controls (includes pistol grip)	\$64,890.00
Required	KI-163 Full-Flow Oil Filter	\$639.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Optional	Pneumatic Front Door Opener	\$11,180.00
Required	C034-5 Pop-Out Float Overhaul	\$75,200.00
	(includes new floats, covers & cylinder exchange)	
Required	C034-4 Fixed Float Overhaul (includes new floats)	\$36,200.00
Required	KI-196-1 or -2 Fuel Bladder Tanks	\$15,000.00
Required	Camshaft & Valve Train Parts (flat)	\$6,512.00
Required	Camshaft & Valve Train Parts (roller)	\$14,832.00
Required	KI-275-2 Cockpit Camera	\$3,920.00
Optional	G084-3 Impact Resistant Windshields	\$15,850.00
Optional, 10001 & subsequent	Air Conditioning	\$26,100.00

Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet (charcoal only) and headliner. Additional cost for leather seats is \$1,820.00/Cadet \$920.00. Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs). Crating \$8,000.00. Production-equivalent minor upgrades and up-to-date Service Bulletin compliance. The RHC Limited Parts Warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours, whichever event occurs first; provided the part has been subjected to normal use and service. Specifications and prices are subject to change without prior notice.

Prices net RHC factory, no Dealer/Service Center discounts apply.

Robinson Helicopter Company

2901 Airport Drive • Torrance • CA • 90505 • 310-539-0508 • www.robinsonheli.com



Effective 01 March 2025

Required

KI-218 Full Throttle Caution Light Upgrade Kits

R22 SL #66

KI-218-1A \$278.00 if throttle bellcrank includes A607-2 Cam
KI-218-1B \$723.00 if throttle bellcrank doesn't include A607-2 Cam

R44 Raven SL #52

KI-218-2A \$340.00 if throttle bellcrank includes A607-2 Cam
KI-218-2B \$984.00 if throttle bellcrank doesn't include A607-2 Cam

R44 Raven II without Air Conditioning

KI-218-3A \$969.00 if throttle bellcrank doesn't include A534-1 Stop
KI-218-3B \$366.00 if throttle bellcrank includes A534-1 Stop

R44 Raven II with Air Conditioning

KI-218-3C \$340.00

4400-Hour Parts

R22 Beta & Beta II

A020-90 (replaces A020-2) Upper Frame \$6,200.00

A023-22 Tailcone \$6,650.00

A023-23 Tailcone \$6,650.00

A046-2 Lower R/H Frame \$2,710.00

A062-1 TR Hub \$1,620.00

B370-1 MR Hub \$2,010.00

R44 Raven & Raven II

C023-1 STD Tailcone \$10,600.00

C023-4 Tailcone, ENG \$14,600.00

C023-14 Tailcone, 5 Antenna Mounts \$10,900.00

C023-15 Tailcone, 3 Antenna Mounts & VOR Antennas \$10,800.00

C044-1 Horizontal Stabilizer \$3,750.00

Painting Options

Available in Robinson white with choice of solid trim color (non-metallic) at no additional charge.

R22 Beta & Beta II

Optional base colors, except black or metallic, are available for an additional \$1,300.00. Metallic base is \$1,700.00. Metallic trim is \$900.00. Solid black or metallic black with or without trim is \$2,300.00.

R44 Raven, Raven II & Cadet

Optional base colors, except black or metallic, are available for an additional \$1,800.00. Metallic base is \$2,400.00. Metallic trim is \$1,200.00. Solid black or metallic black with or without trim is \$3,300.00.

The Astro paint scheme is available for an additional \$4,300.00.

Please visit our website at www.RobinsonHeli.com for available colors.

Robinson Helicopter Company

2901 Airport Drive • Torrance • CA • 90505 • 310-539-0508 • www.robsonheli.com