



Pricing for R66 2000-Hour Maintenance and Inspection Performed at RHC

Below pricing for R66 2000-Hour Maintenance and Inspection performed at RHC effective **01 March 2025**. Base price is for an airworthy R66 properly maintained, undamaged and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4000-hours (parts listed on R66 SL-49), or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes RR300 engine 2000-Hour Preventative Maintenance Inspection (PMI) performed by a Rolls-Royce Authorized Maintenance, Repair & Overhaul Center (AMROC) and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2000-hours:

Exchange Components

- C005 MR Blade & Spindle Assembly (set)
- C021 TR Gearbox
- F001 MR Gearbox Sub-Assembly
 - Includes:
 - C017 Swashplate
 - D211 Hydraulic Reservoir
 - D212 Hydraulic Servos
 - D500 Pump Assemblies
 - F006 MR Gearbox
 - G201 Servo Support Frame (new)
- F018 Clutch
- F649 Engine Oil Cooler

New Parts

- A120 Bellcrank
- A522 Control Cables
- A947 Flex Plates
- B345 TR Pitch Links
- C005 MR Hub
- C008 TR Assembly
- C522 Control Cables
- C947 Flex Plates
- D224 TR Drive Shaft
- F020 Upper Frame
- F173 Exhaust Support Struts
- F235 Upper Frame Struts
- F252 Upper Frame Strut
- F642 Engine Shaft Weldment
- C031 TR Pitch Control
- F792 Dual Tachometer
- C649 Oil Cooler
- Various small parts & hardware

Base Price (does not include upgrades, 4000-hr parts, tailcone & stabilizer) \$388,900.00

Base price also includes:

- Complete refurbishing of helicopter interior including new seats (leather), carpet (charcoal only) and headliner.
 - Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs). Crating \$9,000.00.
 - Production-equivalent minor upgrades and up-to-date Service Bulletin compliance.

Optional equipment:

- DER-approved repairs.
 - C034-4 Fixed float overhaul (includes new floats) \$36,200.00.
- C034-5 Pop-out float overhaul (includes new floats, covers & cylinder exchange) \$75,300.00.
 - RR300 4th stage wheel replacement (SB A-72-024). Determined by vendor.
 - G084-1 Impact resistant windshields \$16,138.50.

Required

- KI-6602-1 4000-Hour Tailcone & Horizontal Stabilizer Kit \$19,700.00
- KI-6602-2 2000-Hour Tailcone & Horizontal Stabilizer Kit \$15,000.00
- KI-275-3 Cockpit Camera \$3,860.00

The RHC Limited Parts Warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours, whichever event occurs first; provided, the part has been subjected to normal use and service. The RR300 Rolls-Royce engine warranty is determined by the independent repair/overhaul facility. Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply.



Effective 01 March 2025

R66 2000-Hour G010-1 Aux Fuel Tank Installation

Serial Number 0620 thru 0718 \$46,811.00

- Aux Tank Installation (\$42,900.00)
- D835-2 Harness Assembly, Adapter (\$552.00)
- D835-3 Harness Assembly, Cabin (\$2,140.00)
- D835-4 Harness Assembly, Time Delay Relay (\$259.00)
- 6 hours additional labor (\$960.00)

Serial Number 0719 and subsequent \$42,900.00

- Aux Tank Installation

PAINTING OPTIONS

Available in Robinson White with choice of solid trim color (non-metallic) at no extra charge.

Optional base colors, except black or metallic, are available for an additional \$1,800.00. Metallic base is \$2,400.00. Metallic trim is \$1,200.00. Solid black or metallic black with or without trim is \$3,300.00.

Please visit our website at www.robinsonheli.com for available colors.